

Terminal connection diagram for general-purpose electric motors

Table 1

Output	Connection pattern
0.2~7.5kW	
5.5~37kW	
45~90kW	

1) Explanation of terms

SOURCE: Power source

STARTER: Star-delta starter

2) When connected as shown in the figure, the motor will rotate counterclockwise when viewed from the shaft end of the motor.

3) The figure shows typical example. Please refer to the instruction manual of the motor before connecting the wires.